



## Respect the Arc Flash Boundary

Arc flash temperatures can exceed 35,000°F in an instant. Always verify boundaries and wear the required arc-rated PPE before starting work. Never assume equipment is de-energized - test before touch.