



## Safety Message of the Day for IMEA Members



### Night Work & Low Visibility Hazards

If you can't see it, you can't control it

- Reduced visibility increases the risk of falls, equipment strikes, and missed hazards.
- Use high-lumen headlamps, area lights, and reflective PPE.
- Mark hazards clearly with glow tape or lights (trenches, guy wires, drop-offs).
- Ensure truck-mounted lighting doesn't create glare or deep shadows.
- Fatigue is amplified at night — rotate roles and take breaks as needed.

***Do a “hazard walk” before starting night work — walk the site and identify risks.***