



## **Stop Work for Unsafe Conditions**

If something doesn't look right, stop and reassess the job. Damaged equipment, missing labels, or unclear procedures increase arc flash risk. Everyone has the authority and responsibility to stop unsafe work.