




Safety Message of the Day for IMEA Members



Identify and Control All Energy Sources Safety Message

Before you touch anything, know what you're working on.

1. Verify all sources: primary lines, backfeeds, generators, capacitors.
2. Use proper lockout/tagout where applicable.
3. Treat all lines as energized until they're tested and grounded.
4. Test, then ground. Never assume it's dead because someone "said so."