



Safety Message of the Day for IMEA Members



Tools and Equipment Safety Message

OSHA 29 CFR 1910.269(a)(2)(i) & (d)(2)

- Tools, equipment, and PPE shall be inspected before use.
- Cold temperatures can cause materials to become brittle or malfunction—remove damaged equipment from service immediately.